

The SID was located on B1050 facing Somersham from 28/06/2019 to 25/07/2019

**From Somersham**

Less than 30 mph 58%

Between 30 and 40 mph 38%

With the remaining 4% over 40 mph.

29 recordings were above 60 mph

**From Earith**

Less than 30 mph 67%

Between 30 and 40 mph 31%

With the remaining 2% over 40 mph.


17 recordings were above 60 mph



Average and Maximum speed

Speed distribution (Pie)

Raw data




Evaluation time 28 June 2019,10:00 - 25 July 2019,19:00						
Speed limit	30 mph	Values	Vehicles	Vd[km/h]	Vmax[mph]	V85 mph]
Speed violations	32.88 %	207199	23893	28	over 70	34
ADT	873					
AYT	318645					
Evaluation direction	Departing					
Author:						
Comment:						
Location:	B1050 Tidley Cross					
Arriving vehicles from:	Somersham					
Departing vehicles to:						

Average and Maximum speed

Speed distribution (Pie)

Raw data



Evaluation time		28 June 2019,10:00 - 25 July 2019,19:00				
Speed limit	30 mph	Values	Vehicles	Vd[mph]	Vmax[km/h]	V85 [km/h]
Speed violations	42.37 %	147925	18423	30	over 70	35
ADT	673					
AYT	245645					
Evaluation direction	Arriving					
Author:						
Comment:						
Location:	B1050 Tidley Cross					
Arriving vehicles from:	Somersham					
Departing vehicles to:						